
Superstart quick connector



: 7 or 8 mm (PE40/

(barb connectors)

: 32 mm (or larger)

max. 2.4 mm)

: 300 l/h

: 8 bar

: acetal

LDPE / wall thickness

The Superstart quick connector is mainly applied in open field irrigation systems. The Superstart quick connector allows for fast and smooth coupling and uncoupling of sprinklers from a PE or PVC sub main line.

The Superstart quick connector may sometimes become separate unintentionally. To prevent from causing damage Netafim developed a new Super start quick connector, adding 2 extra clamps to secure the connector. This results in no more uncontrolled disconnections while maintaining sprinkler connection flexibility.

Displayed materials

FXN quick connector
cover PE 12mm
FXN quick connector
PE 12 Male
PE quick connector plug barb
Female

The connector fits a LDPE 12x1 until 12x1,5 mm. The minimal line diameter is 32 mm with a variable width of 2 until 6 mm.

The PE connector may be replaced with a $\frac{1}{2}$ " thread connector. This makes the connector suitable for connecting to drill saddles or FlexNet sockets.

65080-005210 FXN quick connector plug ½" Female

APPLICATION Outdoor irrigation

CHARACTERISTICS

 Quick disconnection of sprinklers from PE lines, where extra connection safety is required and applied with extra clamps

TECHNICAL DATA

Punch diameter

Maximum flow rate Maximum pressure Material

LDPE line assembly

INSTALLATION & MAINTENANCE

- For assembly of a few Superstart connectors in LDPE tube we would advise the usage of a manual punch 7 - 8 mm (45000-001400).
- For the installation of large quantities of Superstart connectors on pipes with a diameter of 40 mm or larger and wall thickness of 2.5 to 3.0 mm, a special tool, the Superstart inserter (45000-002010) is available for speeding up and easing installation work.
- An Allen key and wrange is required for FXN quick connector plug ½" assembly.

